

TECHNICAL GROUP BULLETIN

12-18-2014

BLUESTAR TIRES

TIRE SAFETY RECALL

**PRODUCT
AFFECTED:** 8-14.5/G 14PR BLUESTAR LQ225
DOT 69ML NR **0913** TO **3214**

**PRODUCT
CODE:** Misc

REASON: Sidewall blister develops in upper sidewall during use indicating possible separation. The sidewall blister could pop leading to rapid air pressure loss which could then lead to loss of control of vehicle, increasing the risk of a crash leading to property damage or injury.



WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment