

TECHNICAL GROUP BULLETIN

7-11-2017

GITI/PRIMEWELL TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: **PRIMWELL VALERA TOURING II**

185/65R14 88H Y9 **1415 TO 5216**

195/60R15 88H Y9 **1415 TO 5216**

205/55R16 91H Y9 **2714 TO 5216**

205/60R16 92V Y9 **3114 TO 5216**

215/60R17 96H Y9 **2714 TO 4816**

235/60R17 102T Y9 **3614 TO 4716**

ARTICLE NUMBER: **Misc**

REASON: These tires may be prone to developing a crack in the lower sidewall area of the tire. The crack can manifest into an external visible crack usually after the tire is in service for several months. The crack could result in air pressure loss.



WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment