

TECHNICAL GROUP BULLETIN

9-22-2022

22T014

ZEETEX AT TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: ZEETEX AT 1000

LT235/80R17/E 120/117R	DOT	109 -- ---- 0619 TO 2522
LT275/70R18/E 125/122S	DOT	109 -- ---- 1319 TO 2522
LT285/75R16/E 126/123R	DOT	109 -- ---- 0417 TO 2522
LT275/65R20/E 126/123S	DOT	109 -- ---- 2020 TO 2522
LT245/75R17/E 121/118R	DOT	109 -- ---- 4414 TO 2522



ARTICLE NUMBER: MISC

REASON: The sidewall may prematurely separate near the bead area of the tire. As such, these tires fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 139, "New Pneumatic Radial Tires for Light Vehicles."

Store Instructions:

Removing Recalled Tires from Vehicles:

1. Follow your normal adjustment process
2. Write up as a "Manufacturer Adjustable Condition" on invoice
3. Select adjustment type "9-Recall/MFG Replacement Program"
4. Enter complete D.O.T. number and Full Tread Depth measurements
5. Print & stick Adjustment label on tire(s)
6. Stage with your other adjustment tires
7. **No charge** to customer for replacement tire(s)
8. **No charge** to customer for Certification renewal(s), if they were originally purchased
9. **No charge** for mounting, balancing, or any type of labor
10. Offer Certifications on replacement tire(s), if none were originally purchased

TECHNICAL GROUP BULLETIN

Warehouse Instructions:

Recalled Tires from Vehicle:

1. This is a manufacturer we do not deal with and will need to be treated as a write off.
2. Disable and Discard tire.