

TECHNICAL GROUP BULLETIN

7-17-2015

CONTINENTAL TIRES

TIRE SAFETY RECALL

PRODUCT 225/45R17 91H SL Conti ProContact
AFFECTED: DOT TIN Range:
P5TY PXH6 **0815** TO P5TY PXH6 **1915**

PRODUCT 26590
CODE:

REASON: The tires may experience loss of air pressure.

ONLY TIRES WITH THESE DOT'S ARE AFFECTED

NEW PRODUCT:

Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective

1. Transfer to warehouse
2. Under comments write "Tire Safety Recall"
3. Return through normal adjustment process

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment