

# TECHNICAL GROUP BULLETIN

5-9-2023

## TRICO WIPER BEAM BLADES

PRODUCT  
AFFECTED: **All TRICO WIPERS**

ARTICLE  
NUMBER: **ALL**

**REASON: BEAM WIPERS:**

In some instances, we have discovered an issue where the wiper does not lock into place sufficiently. (see Images) We have no known instance of any safety issue. **This is a quality issue.**

Reinforce our training to verify the beam style blades are installed correctly by pushing on the blade after it has been installed

### **BEAM WIPERS INSTALLATION:**

When installing wiper blades align the wiper as shown and pull on it until you hear a click. Then verify that it is engaged by pushing on the blade. If it comes back off with little effort, then select another blade and contact your supervisor.

