

Cordless Impacts QRG for Store Managers

Introduction

The ½" Milwaukee Cordless Impact Driver has been updated with new programming specifically for Discount Tire/America's Tire which requires a minor change in the install process. Review the information below to ensure that your employees understand the updated process expectations and that any existing impact drivers are handled appropriately.

Before Putting into Service

Once the new ½" Milwaukee Cordless Impact Drivers are delivered to your store, and before putting them into service, ensure:

Step	Action
1	All employees have reviewed the Using Cordless Impacts Operational Best Practice, understand the process change, and have completed the Acknowledgement in the LMS.
2	If cordless impacts are replacing pneumatic impact drivers remove from service and handle appropriately. (See <i>What to do With Existing Tools</i> section below.)
3	Once the above steps have been completed, log into the LMS and complete the Milwaukee Cordless Impact Drivers Update for Store Managers Acknowledgement.

What to do With Existing Tools

½" Pneumatic Impact Drivers: Keep as many as is needed for your store to service dually and heavy trucks. The rest should be removed from service.

Non-Milwaukee Cordless Impact Drivers: These should be discarded immediately, as they are not approved for use.

½" Milwaukee Cordless Impact Driver: All Milwaukee Impact Drivers purchased by stores through non-Discount Tire approved vendors need to be sent to the warehouse to be evaluated by the warehouse manager.

Contact

If you have any additional questions, please contact DTC_Equipmentquality@discounttire.com for more information.