

TECHNICAL GROUP BULLETIN

3-24-2014

GORILLA LUG NUTS MANUFACTURER RETURN


PRODUCT
AFFECTED:

O.E. GM replacement lug nuts

PRODUCT CODE: **Misc**

REASON:

The lug nut was designed too tall and causes the plastic lug cover to bottom out preventing the center cap from tightening properly



NEW PRODUCT:

Remove affected product from inventory

1. Transfer to warehouse
2. Under comments write "Manufacturer Return"
3. Warehouse will return to Gorilla

Replacement Lug nuts:

WEST COAST ACCESSORIES PN#W6015C



W6015C