

TECHNICAL GROUP BULLETIN

11-20-2017

ANTARES TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: **LT225/75R16/E 118/116S Antares
Comfort A5 with the DOT of:
KBU5 NR 1916 TO 2016**

ARTICLE NUMBER: **MISC**

REASON: **Separation of sidewall (voids) around the bead could
happen during driving. Sidewall bulge may occur.**



These tires could have been sold by Walmart

WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment