

TECHNICAL GROUP BULLETIN

8-15-2013

AUTOGUARD TIRES RECALL

PRODUCT AFFECTED: **LT245/75R16/E 120S
AUTOGUARD RADIAL AP**

PRODUCT CODE: **MISC**

REASON: The tire did not pass the endurance test in FMVSS NO.139 and the Max. Load of 3415 IBS for single and 3085 IBS for dual is wrong, the correct is 3042 IBS for single and 2778 IBS for dual.



**There were 2711 of these tires imported to the U.S...
These tires would have been sold through wholesalers or
independent tire dealers.**

WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment