

TECHNICAL GROUP BULLETIN

6-17-2013

GITI TIRES VOLUNTARY RECALL

PRODUCT AFFECTED: **P235/60R16 99T GITI RUNWAY
ENDURO 816**
DOT: **5WWKOOA 0213**

PRODUCT CODE: **MISC**

REASON: **Due to a tire mold issue, the tires may develop splits in the shoulder.**



This is product that would only have been purchased from a wholesaler.

WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment