

TECHNICAL GROUP BULLETIN

8-18-2015

HERCULES TIRES VOLUNTARY RECALL

PRODUCT AFFECTED:	HERCULES ALL-TRAC A/T			
	235/70R16	106T	DOT JEKJ ECP	2508 TO 2110
	235/75R15 XL	109T	DOT JEKK DCP	2708 TO 2110
	245/70R16	107T	DOT JELJ ECP	2508 TO 2110
	255/70R16	111T	DOT JEMJ ECP	2508 TO 2110
	265/70R16	112T	DOT JENJ ECP	2508 TO 2110
	265/75R16	116T	DOT JENK ECP	3008 TO 2110
	275/70R16	114T	DOT JERJ ECP	1309 TO 2110

**ARTICLE
NUMBER:** MSC

REASON: A tire tread separation may result in sudden air loss, increasing the risk of a vehicle crash

ONLY TIRES WITH THIS DOT ARE AFFECTED



RECALLED TIRES (driven-on)

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- Process as normal adjustment