

# TECHNICAL GROUP BULLETIN

---

2-26-2013

## HERCULES TIRES RECALL

PRODUCT AFFECTED: **Hercules ALL TRAC A/T**

<b>LT215/85R16 115/1128</b>	<b>JEHMECL0909 to 4010</b>
<b>LT235/85R16 120/1168</b>	<b>JEHMECL0409 to 4010</b>
<b>LT245/75R16 120/1168</b>	<b>JEHMECL5008 to 4010</b>
<b>LT265/75R16 123/1208</b>	<b>JEHMECL0509 to 4010</b>
<b>LT265/70R17121/1188</b>	<b>JEHMECL 0909 to 4010</b>
<b>LT245/75R17121/1188</b>	<b>JEHMECL 1009 to 4010</b>
<b>LT225/75R16 115/1128</b>	<b>JEHMECL0909 to 4010</b>

PRODUCT CODE: **Misc**

REASON: **These tires may experience in service belt and tread separations.**



# TECHNICAL GROUP BULLETIN

---

## NEW PRODUCT:

**Remove affected product from inventory /  
showroom displays and return to Adjustment  
warehouse as New Defective**

1. Transfer to warehouse
2. Under comments write "Voluntary Recall"
3. Return to manufacturer

## WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment