

TECHNICAL GROUP BULLETIN

6-9-2015

JINYU/EVERGREEN TIRES

TIRE RECALL

PRODUCT AFFECTED: LT225/75R16 JINYU YS78 /EVERGREEN ES89
DOT TIN Range: KE-- ---- **1611** thru KE-- ---- **4314**

PRODUCT CODE: Misc

REASON: The affected tires may not be able to Properly dissipate heat, and as a result, the tire belts may separate.



WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment