

TECHNICAL GROUP BULLETIN

5-29-2014

MOMO WHEELS

FITMENT INSPECTION

PRODUCT
AFFECTED: **MOMWI2, MOMWIP**

PRODUCT CODE: **ALL**

REASON: Momo wheels manufactured these wheels out of two different plants and some of these wheels have thicker mounting pads. The wheels with thicker mounting pads will require the use of ET lug nuts or longer lug bolts

We will be mailing letters to customer that purchased these wheels. We are asking the customer to contact us and make an appointment to have their wheels inspected.

What to do when customer comes in.

Inspect the thread engagement of the wheel and use ET lugs or longer lug bolts when necessary. If proper thread engagement is not possible replace wheels as an adjustment.