

TECHNICAL GROUP BULLETIN

7-17-2015

PATHFINDER SPORT SAT TIRES

TIRE SAFETY RECALL

**PRODUCT
AFFECTED:** LT 265/70R17/E 121S PATHFINDER SPORT SAT
LT 265/75R16/E 123Q PATHFINDER SPORT SAT
LT 275/65R18/E 123S PATHFINDER SPORT SAT
LT 245/75R17/E 121R PATHFINDER SPORT SAT

**PRODUCT
CODE:** 19123, 17983, 19124, 17970

REASON: The tires may experience tread separation.

NEW PRODUCT:

**Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective**

- 1. Transfer to warehouse**
- 2. Under comments write "Tire Safety Recall"**
- 3. Return through normal adjustment process**

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"**
- Select adjustment type "9-Recall / MFG Replacement Program"**
- Enter complete D.O.T. number and full tread depth.**
- No charge for replacement**
- No charge for Certificate renewal (if purchased originally).**
- Offer Certificates on the replacement tires (if not purchased originally).**
- Process as normal adjustment**