

TECHNICAL GROUP BULLETIN

2-14-2018

SENTURY TIRE

PRODUCT INSPECTION/RETURN

PRODUCT AFFECTED: **225/60R16 98H SENTURY TOURING**

ARTICLE NUMBER: **29234**

REASON: Some of these tires may not have a full DOT on either sidewall.

ACTION: Inspect all inventories and report the quantity of tires you find without a full DOT on either sidewall to Gary.ruede@discounttire.com.

NEW PRODUCT:

Remove affected product from inventory / showroom displays and return to Adjustment warehouse as New Defective

1. Transfer to warehouse using article number
2. Under comments write "New Defect"
3. Return through normal adjustment process