

TECHNICAL GROUP BULLETIN

3-28-2019

TASKMASTER TIRE

PRODUCT REMOVAL

PRODUCT AFFECTED: **5.70-D8/C Taskmaster Contender**

ARTICLE NUMBER: **39120**

REASON: All tires under this product code are to be removed from inventory following the New Product instructions below.

NEW PRODUCT:

1. Create an RTV PO to Taskmaster for the quantity of tires you have found with the Mislabel
 - 1a. Under **Comments**: write "Mislabel"
 - 1b. Under **Returned By**: select "Other"
2. Corporate will compile all RTV PO's and send to Taskmaster. Credit issued will be allocated back to appropriate stores.
3. If your store is visited by a warehouse, they will cut the bead and dispose of the tire at the store. If your store is Not visited by a warehouse, store is to disable the tire and dispose of properly.

*Tires that have been sold will be recalled by Taskmaster as this is a labeling issue. The tire does carry the load it is supposed to so there is not a safety concern.