

# TECHNICAL GROUP BULLETIN

12-9-2014

## TOWMAX STR TIRES

### TIRE SAFETY RECALL

**PRODUCT  
AFFECTED:** ST225/75R15/D TOWMAX STR  
DOT ADB4 GPD **2414** TO **4214**

**PRODUCT  
CODE:** Misc

**REASON:** The affected tires may have Incorrect Load Capacity and Inflation Pressure Stampings. The ST225/75 R15 Towmax 8PR LR-D is stamped with the Load Capacity and Inflation Pressure Stampings of the 10 Ply Rating version of the same size tire.



### WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment