

# TECHNICAL GROUP BULLETIN

9-6-2017

## TRIANGLE TIRE SAFETY RECALL

PRODUCT AFFECTED: **ST225/75R15 TRIANGLE TR643**  
**DOT of: 2VMC 0516 TO 0617**

ARTICLE NUMBER: **MISC**

REASON: **These tires were made with a defect in the mold  
that caused a hole in the sidewall of the tire**



### WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment