

TECHNICAL GROUP BULLETIN

7-8-2014

VAIL SPORT ST LH 99 VOLUNTARY RECALL

PRODUCT
AFFECTED: **ST225/75D15/D Vail Sport ST LH 99**
DOT 69 1412 TO 0513

PRODUCT CODE: **Misc**

REASON: **The affected tires may not be marked with the load range letter designation. As such, these tires fail to comply with the requirements of Federal Motor Vehicle Safety Standard No. 119**



NEW PRODUCT:

Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective

1. Transfer to warehouse
2. Under comments write "Voluntary Recall"
3. Return through normal adjustment process

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment