

# TECHNICAL GROUP BULLETIN

---

6-20-2019

## SENTURY TIRE

### PRODUCT INSPECTION/RETURN

PRODUCT AFFECTED: **225/60R16 98H SENTURY TOURING**  
**215/60R16 95H SENTURY TOURING**

ARTICLE NUMBER: **29234, 29217**

REASON: Some of these tires may not have a full DOT on either sidewall.

**ACTION: Inspect all inventories and report the quantity of tires you find without a full DOT on either sidewall to [Gary.ruede@discounttire.com](mailto:Gary.ruede@discounttire.com).**

#### **NEW PRODUCT:**

**Remove affected product from inventory /  
showroom displays and return to Adjustment  
warehouse.**

1. Create STO transfer to warehouse using article number
2. Under comments write "NO DOT"