

TECHNICAL GROUP BULLETIN

5-12-2021

TASKMASTER TIRE CONTENDER

**PRODUCT
AFFECTED:**

Contender Trail Bias

205/90D15 is labeled as a 205/95D15

**ARTICLE
NUMBER:**

39127

REASON:

Label company misprinted labels with a "5" instead of a "0".



CORRECT LABEL ABOVE

Store Instructions:

Remove Label and label correctly.

Inventory and barcode scan are correct.