

TECHNICAL GROUP BULLETIN

2-28-2018

COOPER TIRE VOLUNTARY RECALL

**PRODUCT
AFFECTED:**

MASTER CRAFT AVENGER GT
P225/70R14 98T DOT R7FC FF6 **0617 TO 0717**

MASTERCRAFT MC-440
185/60R15 R790 FW8 **0617 TO 0717**
215/60R16 R75M FW8 **0617 TO 0717**
225/60R17 R741 FW8 **0617**
205/55R16 R70F FW9 **0617 TO 0717**

MASTERCRAFT A/S IV
P205/75R15 R7UL FEB **0617 TO 0717**
P235/75R15 R7HL FEB **0617 TO 0717**

STARFIRE RS-C 2.0
205/55R16 R7OF FW9 **0617 TO 0717**
205/55R16 R7OF LMU **0617 TO 0717**
215/60R16 R75M LDJ **0617 TO 0717**

STARFIRE SF-340
P185/60R15 R7MF XKV **0617 TO 0717**
P215/60R16 R7X8 XKV **0617 TO 0717**
P215/65R16 R72H XKV **0617 TO 0717**

ARTICLE NUMBER: MISC, 28013, 28010

REASON: The belt packages of these tires were made with an incorrect rubber compound which may lead to ride disturbances or tread separation

NEW PRODUCT:

Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective

1. Transfer to warehouse under article number
2. Under comments write "Voluntary Recall"
3. Return through normal adjustment process

TECHNICAL GROUP BULLETIN

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment