

TECHNICAL GROUP BULLETIN

9-12-2016

DUNLOP TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: **P205/70R15 95T Dunlop SP 50 with
the DOT of:
M6MO LTER 4912 TO 0314**

ARTICLE NUMBER: **28278**

REASON: **The tire tread of the affected tires may chunk off
if driven on with low tire pressure. As such,
these tires fail to comply with the requirements
of Federal Motor Vehicle Safety Standard
(FMVSS) number 139, "New Pneumatic Radial
Tires for Light Vehicles."**

NEW PRODUCT:

**Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective**

- 1. Transfer to warehouse using article number 28278**
- 2. Under comments write "Voluntary Recall"**
- 3. Return through normal adjustment process**

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"**
- Select adjustment type "9-Recall/MFG Replacement Program"**
- Enter complete D.O.T. number and full tread depth.**
- No charge for replacement**
- No charge for Certificate renewal (if purchased originally).**
- Offer Certificates on the replacement tires (if not purchased originally).**
- Process as normal adjustment**