

TECHNICAL GROUP BULLETIN

2-28-2018

GT TIRE

PRODUCT INSPECTION/RETURN

PRODUCT AFFECTED: **215/60R16 95H GT TOURING VP
PLUS**

ARTICLE NUMBER: **31664**

REASON: **Some of these tires may not have a full DOT on either sidewall.**

ACTION: Inspect all inventories and report the quantity of tires you find without a full DOT on either sidewall to Gary.ruede@discounttire.com.

NEW PRODUCT:

Remove affected product from inventory / showroom displays and return to Adjustment warehouse as New Defective

- 1. Transfer to warehouse using article number**
- 2. Under comments write "New Defect"**
- 3. Return through normal adjustment process**