

# TECHNICAL GROUP BULLETIN

11-15-2016

## GITI / PRIMEWELL TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: GITI PRIMEWELL VALERA TOURING/ TOURING II  
205/50R17 93V DOT Y9HF CLVX **1814 TO 3516**  
215/50R17 95V DOT Y9HH CLVX **2214 TO 3516**  
225/50R17 94V DOT Y9HJ CLVX **1614 TO 3416**  
225/50R18 95T DOT Y9FH CLTX **1914 TO 3416**

ARTICLE NUMBER: **MISC**

REASON: The affected replacement passenger car tires may develop cracks in the lower sidewall, potentially resulting in a loss of air.



### WHEN REMOVING RECALLED TIRES

- Key as a “Manufacturer Adjustable Condition”
- Select adjustment type “9-Recall/MFG Replacement Program”
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment