

# TECHNICAL GROUP BULLETIN

---

3-4-2019

## HANKOOK TIRE

### PRODUCT INSPECTION/RETURN

PRODUCT AFFECTED: **LT265/75R16/E 123S PATHFINDER  
AT**

ARTICLE NUMBER: **26181**

REASON: **Some of these tires may not have a full DOT on either sidewall.**

**ACTION: Inspect all inventories and report the quantity of tires you find without a full DOT on either sidewall to [Gary.ruede@discounttire.com](mailto:Gary.ruede@discounttire.com).**

#### **NEW PRODUCT:**

**Remove affected product from inventory / showroom displays and return to Adjustment warehouse as New Defective**

- 1. Transfer to warehouse using article number**
- 2. Under comments write "New Defect"**
- 3. Return through normal adjustment process**