

TECHNICAL GROUP BULLETIN

7-8-2016

HANKOOK TIRE STOP SELL

PRODUCT AFFECTED: **LT275/65R20/E 126
HANKOOOK ATM RF10**

ARTICLE NUMBER: **10852**

REASON: **These tires beads will not seat on several O.E. wheels**



NEW PRODUCT:

Hold all products at the store until further notice.