

TECHNICAL GROUP BULLETIN

5-8-2018

KUMHO TIRE VOLUNTARY RECALL

PRODUCT AFFECTED: **P225/65R17 100H
KUMHO SOLUS KH16 with the
DOT of: 000 E6NR 1317**

ARTICLE NUMBER: **18538**

REASON: **Belt separation might occur while being
operated under severe conditions and
could potentially result in a tire failure.**

NEW PRODUCT:

**Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective**

- 1. Transfer to warehouse using the article number**
- 2. Under comments write "Voluntary Recall"**
- 3. Return through normal adjustment process**

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"**
- Select adjustment type "9-Recall/MFG Replacement Program"**
- Enter complete D.O.T. number and full tread depth.**
- No charge for replacement**
- No charge for Certificate renewal (if purchased originally).**
- Offer Certificates on the replacement tires (if not purchased originally).**
- Process as normal adjustment**