

TECHNICAL GROUP BULLETIN

5-19-2016

PIRELLI TIRE SAFETY RECALL

**PRODUCT
AFFECTED:** 225/50R15 91Y Pirelli PZERO Trofeo
tires with the
DOT of XJBU U785 _____

**ARTICLE
NUMBER:** Misc

REASON: The affected tires do not have a full
DOT on either sidewall.
Neither sidewall should have the last 4
numbers which represents the date of
manufacturer

NEW PRODUCT:

Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse as New Defective

1. Transfer to warehouse
2. Under comments write "Recall"
3. Return through normal adjustment process

WHEN REMOVING RECALLED TIRES

- Key as a "Manufacturer Adjustable Condition"
- Select adjustment type "9-Recall/MFG Replacement Program"
- Enter complete D.O.T. number and full tread depth.
- No charge for replacement
- No charge for Certificate renewal (if purchased originally).
- Offer Certificates on the replacement tires (if not purchased originally).
- Process as normal adjustment