

Rear shock mount on 1999 and newer Ford F250 and F350 models

Filing Instructions: File in the Automotive Service Operation's Notebook
Rear shock mount may be damaged while lifting vehicles. Suggest using the rear axle tube as a jack point instead of the shock mount when lifting these vehicles. It is possible to bend the shock mount, which can result in a \$4,000 repair.

