



General Motors Service and Parts Operations

On October 19th, 2004, a "Stop Sell" was placed on 20-Inch Plus-Size Wheels offered as Chevrolet and GMC Accessories for the 1500 Series Crew Cab models of the Chevrolet Silverado and GMC Sierra (Models CC15543, CK15543, TC15543, TK15543). However, component design changes have recently been made to these vehicles at the following VIN breakpoints, allowing for installation of the 20-Inch Plus-Size Wheels:

1500 Series Crew Cab Model	VIN Breakpoint	Merch Model
Sierra (2WD)	51334993	TC15543
Sierra (4WD)	51334978	TK15543
Sierra Denali (AWD)	51334762	TK15543
Silverado (2WD)	51334946	CC15543
Silverado (4WD)	51335001	CK15543

The 20-Inch Plus-Size Wheels should continue to be restricted for 2004-05 model year 1500 Series Crew Cab models built prior to these VIN breakpoints. The only exception is for those customers who had 20-Inch Plus-Size Wheels installed on their 1500 Series Crew Cab model vehicles prior to October 19th, 2004.

Please reference Technical Service Bulletin 03-03-10-006 to verify all necessary steps are followed to properly install these wheels.

Cary J. Vernier
Brand Quality Manager - GM Accessories & Performance Parts
General Motors Service and Parts Operations
6200 Grand Pointe Drive
Grand Blanc, MI 48439
MC: 484-392-328
Cube R3WS1202
Phone 810-606-4920
Fax 810-606-2150
cary.vernier@gm.com