

# TECHNICAL GROUP BULLETIN

---

4-07-2014

## 16" LAND ROVER WHEELS

### DO NOT INSTALL YOKOHAMA TIRES

**PRODUCT  
AFFECTED:** Yokohama Tires in 16" diameters

**REASON:** Due to dimensional differences and unusual bead humps on 16" Land Rover original equipment wheels, Yokohama tires may not seat without damaging beads or may fail during the inflation process

**SOLUTION:** Sell another brand of tire for these wheel applications.