

# TECHNICAL GROUP BULLETIN

---

7-31-17

## BIMECC LUGS

### STOP SELL FOR FORD 8 & 10 LUG VEHICLES

**PRODUCT  
AFFECTED:** **All 14x1.5, 14x2.0 AND 9/16 duplex  
lugs.**

**REASON:** The dimensions of these lugs are incorrect for applications on Ford 8 and 10 lug vehicles. The length of stud on Ford HD platforms causes the lug to bottom out on the studs and give a false sense of torque.

**ACTION: Do not sell, service or install these lugs for Ford 8 & 10 lug vehicles. Please contact your inventory analyst for additional product.**

**If you have any questions, contact: [Mathew.Rodis@Discounttire.com](mailto:Mathew.Rodis@Discounttire.com)**