

# TECHNICAL GROUP BULLETIN

---

3-26-2014

## MB KRONK 8-LUG WHEEL

- 1. Do Not Sell, Return Stock to Warehouse**
- 2. If Servicing, Replace Product with Appropriate Fitment**

**PRODUCT  
AFFECTED:**

**MB Kronk 8-Lug Wheel**

**PRODUCT  
CODE:**

**16308,16309,16320,16321,16331,16332,  
16333,16338,16339,16340**

**REASON:**

Outer lip is cracking in some applications.



**8-Lug Only**

### **NEW PRODUCT:**

**Transfer to Adjustment Warehouse using inter-company  
shipper.**

### **WHEN SERVICING THE MB KRONK 8-LUG WHEELS**

- Replace Product with Appropriate Fitment**
- Key as an "Adjustment"**
- Select "It's Defective"**
- Select "Other"**
- No charge for replacement**
- Process as normal adjustment**