

TECHNICAL GROUP BULLETIN

4-1-2015

MB WHEELS

LABELING MISPRINT

PRODUCT 16X7.0 +38MM 5-115 MB14
AFFECTED:

PRODUCT 75921
CODE:

REASON: These wheels were mistakenly labeled at the factory as 5-4.5 (5-115). The wheels are actually 5-115.

ACTION: Please correct this by covering up the 5-4.5 labeling on the box using a pen or marker

