

TECHNICAL GROUP BULLETIN

5-6-2014

MB MOTORING WHEELS VOLUNTARY RECALL

PRODUCT
AFFECTED:

All MB Motoring Kronk wheels

PRODUCT CODE: **All product codes under type code MBMKRK**

REASON:

Outer lip may be cracking in some applications.



Liquid Metal will be mailing letters to our customers who purchased this product.

NEW PRODUCT:

**Remove affected product from inventory /
showroom displays and return to Adjustment
warehouse.**

- 1. Transfer to warehouse using product code**
- 2. Under comments write "Voluntary Recall"**
- 3. Return through normal adjustment process**

WHEN REMOVING RECALLED WHEELS

- Key as an "Adjustable Condition"**
- Select adjustment type "IT'S DEFECTIVE"**
- Select "Other"**
- No charge for replacement**
- Process as normal adjustment**