

TECHNICAL GROUP BULLETIN

2-18-2013

UNIQUE 83 STEEL WHEEL

Inspect inventory

PRODUCT AFFECTED: **Unique 83 15x6 4-100/4.5 41B**

PRODUCT CODE: **72515**

REASON: Some of these wheels did not get the center welded in properly.

NEW PRODUCT:

Inspect product inventory / If welds present between barrel and face plate, mark box as checked ok (with date) and replace in inventory. Pictured below is a proper weld.



Product missing welds should be transferred to Adjustment Warehouse using inter-company shipper.