

To be the best

AMERICA'S
TIRE

DISCOUNT
TIRE

DISCOUNT
TIRE DIRECT

MEMORANDUM

TO: AVP's & VP's & Warehouse Managers

FROM: Store Operations

DATE: 2-14-14

RE: Dunk tank pinch point

Certain models of Dunk tanks that we have in our stores may have a pinch/cut point where the dunk plate meets the cylinder nut. If your dunk tank has the wider nut this needs to be replaced.



NEEDS TO BE REPLACED



CORRECT

Certain models of Dunk Tanks that we have in our stores may have a pinch/cut point where the dunk plate meets the cylinder nut due to the lack of a jamb nut on top of the dunk plate. If your Dunk Tank does not have a jamb nut on top of the dunk plate you need to get one.



NEEDS A JAMB NUT



CORRECT

Please check all of the Dunk Tanks in your region and report back to Gary Ruede as to how many cylinder nuts and shaft jamb nuts you need. When we get a total from your region we will send the nuts needed to your regional warehouse. We would like to hear back from everyone by February 28th.

Sincerely,
Store Operations