

TECHNICAL GROUP BULLETIN

6-24-2013

MICHELIN TIRES DO NOT SELL

PRODUCT AFFECTED: **P275/55R20 111T
Michelin LTX M/S2**

PRODUCT CODE: **35436**

REASON: **We have encountered several of these tires
that have pinholes in the sidewall.**

**Required Action: Do not sell. Do not ship tires to
warehouses. We are working with Michelin to resolve this
issue.**