

TECHNICAL GROUP BULLETIN

3-26-2014

MB KRONK 5-LUG & 6-LUG WHEEL

Do Not Sell

**PRODUCT
AFFECTED:**

MB Kronk 5-Lug & 6-Lug Wheel

**PRODUCT
CODE:**

16303,16304,16305,16306,16307,16310
16311,16312,16313,16314,16315,16316
16317,16318,16319,16322,16323,16324
16325,16326,16327,16328,16329,16330
16334,16335,16336,16337

REASON:

Outer lip may be cracking in some applications.



NEW PRODUCT:

Hold inventory in store pending product quality investigation.